



UTILITY WORK REPORT

DATE: August 11, 2025
FOR: City of Wadley
PREPARED BY: Christopher Cooper, Director ROAM Division
REPORTING PERIOD: January 1, 2025 - August 10, 2025

1. New Water Tap Installations

A total of **6 new water taps** were installed throughout the city to support new residential and commercial development. All installations were completed per city specifications and included tapping the existing water main, installing curb stops, meter boxes, and service lines.

Key Locations:

- 20 W. Smith St.
- 34 W. Smith St.
- 205 W. Calhoun St.
- 233 Walden St.

2. Water Main Valve Replacements

We replaced **6 water main valves** that had become non-functional or were leaking. New valves were installed with proper traffic control and all lines were flushed and tested upon completion.

Key Intersections:

- N. Main St. @ Greene St. x 2
- N. Main St. @ Academy St.
- N. Main St. @ Cheatam St.

- 120 S. Main St.
- S. Main St. @ E. Artesian St.

Photo Documentation – Valve Replacements



3. Sewer Tap Installations

6 new sewer taps were installed, providing service to both new developments and replacement laterals for existing structures. All taps were inspected, and testing confirmed proper flow and installation.

Key Locations:

- 233 Walden St.

- 156 Lamb St.
- 20 W. Smith St.
- 120 N. Main St.
- 55 Cheatam St.

Photo Documentation – Sewer Taps and Repairs



4. Water Main Rupture Repairs

We responded to **5 emergency water main ruptures** and completed timely repairs to restore service with minimal disruption. All repairs were disinfected, pressure tested, and logged. Any lead joints or connectors were removed at the time of repair.

Key Repair Locations:

- Walden St. @ E. Railroad St.
- W. Smith St. @ Jordan Circle
- Old 1" galvanized line in front of 20 – 34 W. Smith St. (now abandoned)
- King St.
- Old 1 ½" galvanized line in centerline of W. Calhoun St. (now abandoned)

Photo Documentation – Water Main Repairs





5. General Repairs

We responded to dozens of calls for ruptured service lines, performing sewer lateral cleanouts and repairing leaking curb valves, meters and other equipment. We also installed a new rainwater drainage system behind city hall to mitigate water ponding in the parking lot and adjacent areas. It is currently in service and will be completed with concrete aprons in the next 2 weeks.



6. Lift Stations and Wells

Lift stations and wells are being constantly monitored and repaired when necessary. New controls and capacitors have been installed on 2 lifts stations to provide more reliable service as well as 2 new pumps

to replace worn equipment. The U.S. 1 Bypass lift station has a new submersible pump installed as a temporary measure until a new system can be retrofitted. This removes the bypass pump from the station allowing it to be available if any issues arise at another lift station. Multiple valves, air lines and control hardware have been replaced at both wells to ensure reliable service as well as repairs to the SCADA system which allows us to remotely monitor the system.

Conclusion

All utility work conducted between January and August 2025 has been completed in compliance with local and state codes, and with proper permitting and inspection. We appreciate the continued partnership with the City of Wadley and remain committed to maintaining and improving the city's utility infrastructure.

If you have any questions or would like additional documentation, please don't hesitate to contact us.